



Hall Meter HIS

Valores de tensao em funcao do Led Aceso.

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0

- 1- 0.00 volts
- 2- 0.20 volts
- 3- 0.30 volts
- 4- 0.45 volts
- 5- 0.50 volts
- 6- 0.65 volts
- 7- 0.75 volts
- 8- 0.80 volts
- 9- 0.90 volts
- 10- 1.05 volts